




Vehicle History Report (BC) #: 69062334
Report Date: April 14, 2026 | 9:50 p.m. EDT
Report Status: Complete


2005 HONDA PILOT EXL

Sport utility vehicle | 6 Cylinders | Gas
2HKYF18695H517873
Country of Assembly: Canada
Last Reported Odometer: 85,377 KM


No Reported Accidents >



No Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



5 Service Records Found



U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of April 14, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

This vehicle has been registered in the state of **California** in the **United States**. No major title problems were reported.

We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2004 Nov 15		San Francisco Honda San Francisco, California, United States	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed
2008 Jun 10		Northwest Honda Bellingham, Washington, United States	Vehicle serviced
2018 Jul 12	77,305 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Key(s) (re) programmed New key(s) cut
2019 Aug 27	85,377 KM	OK Tire North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Window motor(s) replaced Window regulator(s) replaced
2019 Dec 7		OK Tire North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Four tires mounted Four tires replaced



Open Recalls

Recall #: S51 | LIGHTING SWITCH HARNESS WEAR Recall Date: 2012 Aug 31

Recall Description

HONDA IS RECALLING CERTAIN MODEL YEAR 2002 THROUGH 2004 CR-V; MODEL YEAR 2003 THROUGH 2005 PILOT; AND MODEL YEAR 2002 AND 2003 CIVIC VEHICLES. IN MARCH 2012, HONDA FILED A DEFECT REPORT TO RECALL CERTAIN MODEL YEAR 2002 THROUGH 2004 CR-V AND CERTAIN MODEL YEAR 2003 PILOT VEHICLES. IN AUGUST 2012, HONDA INFORMED THE AGENCY THAT IT WAS INCLUDING AN ADDITIONAL 820,789 VEHICLES INCLUDING CERTAIN MODEL YEAR 2004 AND 2005 PILOTS AND MODEL YEAR 2002 AND 2003 CIVICS. THE TOTAL NUMBER OF VEHICLES BEING RECALLED IS NOW 1,375,217. DUE TO TENSION FROM THE COMBINATION SWITCH WIRING HARNESS, WEAR ON THE SURFACE OF THE ELECTRICAL TERMINAL CAN OCCUR, YIELDING COPPER OXIDE, WHICH INCREASES ELECTRICAL RESISTANCE. INCREASED ELECTRICAL RESISTANCE MAY CAUSE THE TERMINAL ENDS TO MELT WITHIN THE WIRING HARNESS CONNECTOR.

Remedy

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL REPAIR THE LOW BEAM TERMINAL HARNESS OR REPLACE THE LIGHTING SWITCH AS NECESSARY, FREE OF CHARGE. THE ORIGINAL RECALL BEGAN IN APRIL 2012. OWNERS OF VEHICLES INVOLVED IN THE SEPTEMBER 2012 EXPANSION WILL BE NOTIFIED IN SEPTEMBER 2012. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit Honda's website. (<https://www.honda.ca/recalls>)

Recall #: S88 | VSA ECU MALFUNCTION **Recall Date:** 2013 Mar 14

Recall Description

HONDA IS RECALLING CERTAIN MODEL YEAR 2005 PILOT VEHICLES MANUFACTURED JULY 29, 2004, THROUGH AUGUST 29, 2005; MODEL YEAR 2005-2006 ACURA MDX VEHICLES MANUFACTURED SEPTEMBER 16, 2004, THROUGH SEPTEMBER 22, 2005; AND MODEL YEAR 2005 ACURA RL VEHICLES MANUFACTURED MARCH 1, 2004, THROUGH JUNE 29, 2005. AN ELECTRICAL CAPACITOR MAY HAVE BEEN DAMAGED DURING THE MANUFACTURING OF THE VEHICLE STABILITY ASSIST (VSA) CONTROL MODULE CAUSING INTERMITTENT, AUTOMATIC, MINOR BRAKE APPLICATION. HOWEVER, IF THE DRIVER APPLIES THE BRAKES WHILE THE VSA IS MALFUNCTIONING, THE VEHICLE MAY COME TO AN ABRUPT STOP. ADDITIONALLY, DUE TO A LOOSE GROUND CONNECTION, CERTAIN MODEL YEAR 2005 PILOTS HAVE A VSA SYSTEM THAT MAY APPLY PARTIAL BRAKE FORCE, WITHOUT THE ILLUMINATION OF THE BRAKE LIGHTS, WHETHER OR NOT THE DRIVER IS USING THE BRAKES.

Remedy

OWNERS WILL BE NOTIFIED AND INSTRUCTED TO TAKE THEIR VEHICLES TO A DEALER OF THEIR RESPECTIVE BRAND. THE DEALER WILL INSTALL A PARTIAL WIRING HARNESS CONTAINING A CAPACITOR FOR THE VSA MODULATOR, FREE OF CHARGE. THE AFFECTED MODEL YEAR 2005 PILOTS WILL HAVE THEIR GROUND CONNECTION TIGHTENED. THE RECALL BEGAN ON APRIL 22, 2013. HONDA OWNERS MAY CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-888-234-2138 OR GO TO WWW.RECALLS.HONDA.COM; ACURA OWNERS MAY CONTACT 1-800-382-2238, AND SELECT OPTION 4, OR GO TO WWW.RECALLS.ACURA.COM.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit Honda's website. (<https://www.honda.ca/recalls>)

Recall #: JR4 | PILOT DRIVER AIRBAG **Recall Date:** 2015 Jun 09

Recall Description

HONDA IS CONDUCTING THIS RECALL BECAUSE IT HAS DETERMINED A DEFECT MAY EXIST IN THE DRIVER'S FRONT AIRBAG INFLATOR.

Remedy

PLEASE CALL ANY AUTHORIZED HONDA DEALER AND MAKE AN APPOINTMENT TO HAVE YOUR VEHICLE REPAIRED. YOUR DEALER WILL REPLACE THE DRIVER'S FRONT AIRBAG INFLATOR WITH AN INFLATOR OF A DIFFERENT DESIGN, FREE OF CHARGE. FOR ADDITIONAL INFORMATION AND ASSISTANCE IN LOCATING A HONDA DEALER, PLEASE VISIT WWW.RECALLS.HONDA.COM OR CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-888-234-2138. HONDA'S CAMPAIGN NUMBER FOR THIS RECALL IS JR4.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit Honda's website. (<https://www.honda.ca/recalls>)

Recall #: KA2 | Passenger Airbag Inflator Recall Date: 2016 Jun 14

Recall Description

AMERICAN HONDA MOTOR CO., INC. (HONDA) IS RECALLING CERTAIN MODEL YEAR 2003-2008 HONDA PILOT VEHICLES. THE PASSENGER FRONTAL AIRBAG INFLATOR IN YOUR VEHICLE MAY RUPTURE WHEN DEPLOYING DURING A CRASH. THE POTENTIAL FOR SUCH RUPTURES MAY OCCUR IN SOME OF THE SUBJECT AIRBAG INFLATORS AFTER SEVERAL YEARS OF EXPOSURE TO PERSISTENT CONDITIONS OF HIGH ABSOLUTE HUMIDITY. HONDA SUGGESTS THAT YOU AVOID HAVING A PASSENGER SIT IN THE FRONT PASSENGER'S SEAT UNTIL THE RECALL REPAIR HAS BEEN PERFORMED.

Remedy

PLEASE CALL ANY AUTHORIZED HONDA DEALER AND MAKE AN APPOINTMENT TO HAVE YOUR VEHICLE REPAIRED. YOUR DEALER WILL REPLACE THE PASSENGER'S FRONT AIRBAG INFLATOR WITH AN INFLATOR OF A DIFFERENT DESIGN, FREE OF CHARGE. FOR ADDITIONAL INFORMATION AND ASSISTANCE IN LOCATING A HONDA DEALER, PLEASE VISIT WWW.RECALLS.HONDA.COM OR CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-888-234-2138. HONDA'S CAMPAIGN NUMBER FOR THIS RECALL IS KA2.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit Honda's website. (<https://www.honda.ca/recalls>)








Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2004 Nov 15		San Francisco Honda San Francisco, California, United States	Service Record	Vehicle serviced
 2005 Mar 20		Motor Vehicle Dept. California, United States	DMV Record Adjustment	Title issued or updated Loan or lien reported First Owner Reported Previous Use: Personal lease
 2006 Nov 29		Motor Vehicle Dept. California, United States	DMV Record Adjustment	Title issued or updated Loan or lien reported
2008 Apr 29	71,603 KM	Auto Auction	Auction Announcement	Vehicle sold
2008 May 15		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
	2008 May 15	Vehicle Importer/Exporter	Import Record	<p>From: United States To: Canada</p> <p>This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV (www.riv.ca).</p> <p>Imported Into Canada As: Normal Case/Dossier: Import Date: 5/15/2008 Entered Customs: 5/15/2008 Inspection Date: 6/24/2008</p>
	2008 May 31	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
	2008 Jun 7	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2008 Jun 10	Northwest Honda Bellingham, Washington, United States	Service Record	Vehicle serviced
	2008 Jun 17	64,000 KM Independent Source Vancouver, British Columbia, Canada	Odometer reading	
	2009 Apr 11	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2010 Apr 10	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2011 Apr 30	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2012 Apr 28	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2012 Aug 31	HONDA	Recall	Manufacturer Recall Issued Recall # S51
	2013 Mar 14	HONDA	Recall	Manufacturer Recall Issued Recall # S88
	2013 Apr 27	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2014 Apr 26	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2015 May 2	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Jun 9		HONDA	Recall	Manufacturer Recall Issued Recall # JR4
2016 Apr 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jun 14		HONDA	Recall	Manufacturer Recall Issued Recall # KA2
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Apr 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jul 12	77,305 KM	Service Facility	Service Record	Vehicle serviced
2019 Apr 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 27	85,377 KM	OK Tire North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2019 Dec 7		OK Tire North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2020 Apr 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Apr 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Apr 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Apr 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2024 Apr 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2025 Apr 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2026 Apr 7		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black