




Vehicle History Report (BC) # 71097515
Report Date: July 7, 2026 | 5:39 p.m. EDT
Report Status: Complete

2008 TOYOTA RAV4

Sport utility vehicle | 4 Cylinders | Gas
JTMBD33V386058442
Country of Assembly: Japan
Last Reported Odometer: 122,439 KM



Accident/Damage Records Found




Last Registered In:
British Columbia (Normal)



8 Service Records Found



U.S. History Found



5 Open Recalls Found



Not Actively Declared Stolen



Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of July 07, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

ITMBD33V386058442

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2008 Oct 4	Manitoba, Canada	
	Estimate: Front Estimate Date: n/a	\$85.60
	Claim: Non-collision Front	Not Reported
2019 Aug 23	British Columbia, Canada	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00



Registration

This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Manitoba** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

This vehicle has been registered in the state of **Colorado** in the **United States**. No major title problems were reported.

We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Mar 3		Crown Toyota Winnipeg, Manitoba, Canada	Vehicle serviced - Oil and filter changed - Vehicle washed/detailed
2015 Jul 6	36,429 KM	Crown Toyota Winnipeg, Manitoba, Canada	Vehicle serviced - Recommended maintenance performed - Brakes checked - Engine checked - Vehicle washed/detailed
2016 Apr 22	43,322 KM	Crown Toyota Scion Winnipeg, Manitoba, Canada	Vehicle serviced Front brake pads replaced

ITMBD33V386058442

ODOMETER		SOURCE	DETAILS
2016 Nov 4		Crown Toyota Scion Winnipeg, Manitoba, Canada	Vehicle serviced - Oil and filter changed - Tire condition and pressure checked - Vehicle washed/detailed
2017 Jan 13	47,133 KM	Crown Toyota Scion Winnipeg, Manitoba, Canada	Vehicle serviced Battery/charging system checked
2020 Oct 29	112,693 KM	Kal Tire 044 Kamloops, British Columbia, Canada	Vehicle serviced - One tire balanced - One tire mounted
2021 Feb 3	114,836 KM	Pennzoil 10 Minute Oil Change Centre Kamloops, British Columbia, Canada	Vehicle serviced - Recommended maintenance performed - Differential fluid flushed/changed - Oil and filter changed - Rear differential fluid flushed/changed
2021 Sep 17	122,439 KM	Pennzoil 10 Minute Oil Change Centre Kamloops, British Columbia, Canada	Vehicle serviced Oil and filter changed



Open Recalls

Recall #: 90L | - Potential Floor Mat Interference with Accelerator Pedal Recall Date: 2011 Feb 24

Recall Description

Toyota is recalling certain model year 2008 through 2011 Lexus LX570, 2003 through 2009 Toyota 4Runner, and 2006 through 2010 Rav4 vehicles. The accelerator pedal can get stuck in the wide open position due to its being trapped by an unsecured or incompatible driver's floor mat.

Remedy

The remedy is now available. The safety recall began early April 2011. The remedy will involve modification or replacement of the accelerator pedal and replacement of any Toyota all-weather floor mat. Owners may contact Toyota at 1-800-331-4331 or Lexus at 1-800-255-3987.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website. (<https://www.toyota.ca/toyota/en/owners/recalls>)

Recall #: B0E | - Certain 2007-2008 Model Year RAV4 Vehicles Certain 2008 Model Year Highlander/Highlander HV Vehicles Curtain Shield Airbag (CSA) Sensor - Remedy Parts Available

Recall Date:
2011 Apr 21

Recall Description

Toyota is recalling certain Model Year 2008 Highlander, Highlander Hybrid, and Model Year 2007-2008 RAV4 vehicles. In the curtain shield airbag (CSA) system, there are two sensors in the airbag sensor assembly which are designed to detect vehicle roll angle. If one of these sensors malfunctions, the airbag warning light (malfunction indicator light: mil) will illuminate and the roll detection system will be suspended; however, the airbag csa remains available in the event of a side crash. If both sensors fail nearly simultaneously after initial airbag system check, the CSA and the seat belt pretensioner could be inadvertently activated.

ITMBD33V386058442

Remedy

Toyota will replace the airbag sensor assembly with a new one containing improved roll rate sensors, free of charge. Toyota intends to send an interim owner notification to owners early to mid-May, 2011 when sufficient parts and remedy becomes available. Owners may contact Toyota at 1-800-331-4331.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website. (<https://www.toyota.ca/toyota/en/owners/recalls>)

Recall #: C0M | Remedy Notice - Multiple Models and Model Years - Power Window Master Switch (PWMS)

Recall Date: 2012 Oct
10

Recall Description

Toyota is recalling certain Model Year 2007-2009 Camry, Camry Hybrid, RAV4, Corolla, Corolla Matrix, Tundra, Sequoia, Highlander, Highlander Hybrid, Yaris, Scion xB, Scion xD and Pontiac Vibe vehicles. The power window master switch assemblies in some of these vehicles were built using a less precise process for lubricating the internal components of the switch assemblies. Irregularities in this lubrication process may cause the power window master switch assemblies to malfunction and overheat.

Remedy

Toyota will notify its owners, and dealers will inspect the switch and apply a special grease that inhibits heat build up or replace any switch damaged by the defect, free of charge. Toyota owners that experience a problem with a switch should not attempt to make repairs, but should contact their Toyota dealer or the Toyota customer experience center at 1-800-331-4331. General Motors will contact the Pontiac Vibe owners affected by this recall and GM dealers will inspect and repair switches as necessary. Those owners may contact Pontiac customer care at 1-800-762-2737.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website. (<https://www.toyota.ca/toyota/en/owners/recalls>)

Recall #: G0F | - Remedy Notice 2006 - 2012 Model Year RAV4 2012 - 2014 Model Year RAV4 EV Rear Outboard Seatbelts

Recall Date: 2016 Feb
17

Recall Description

The subject vehicles are equipped with lap-shoulder seatbelts in both second-row outboard seats. There is a possibility that, in the event of a very severe frontal crash, the lap belt webbing could contact a portion of the metal seat cushion frame, become cut, and separate.

Remedy

Toyota dealers will install plastic covers over the metal seat frame at NO CHARGE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website. (<https://www.toyota.ca/toyota/en/owners/recalls>)

Recall #: G0V | - Remedy Notice Certain 2006 to 2011 RAV4 Vehicles Rear Lower Suspension Arm (No. 1) Assemblies

Recall Date: 2016 Aug
10

Recall Description

In the earlier action, if the nuts for adjusting rear wheel alignment were improperly tightened when an alignment was performed, rust could

form on suspension arm threads.

Remedy

The remedy will involve the replacement of BOTH suspension arms and encasing them in epoxy. An alignment will be performed, as well, and warning labels will be applied.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website. (<https://www.toyota.ca/toyota/en/owners/recalls>)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2007 Sep 28		Motor Vehicle Dept. Colorado, United States	DMV Record Adjustment	Loan or lien reported Title or registration issued First Owner Reported Previous Use: Rental
2008 Jun 19	14,328 KM	Auto Auction	Auction Announcement	Listed as a manufacturer vehicle Vehicle sold
2008 Jul 5		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
2008 Jul 5		Vehicle Importer/Exporter	Import Record	From: United States To: Canada This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV (www.riv.ca). Imported Into Canada As: Normal Case/Dossier: Import Date: 7/5/2008 Entered Customs: 7/5/2008 Inspection Date: 7/11/2008
2008 Aug 12		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as blue

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2008 Oct 4		Manitoba, Canada	Non-collision	Front
2008 Oct 4		Insurance Records Manitoba, Canada	Non-collision	Estimate Date: n/a Front
2009 Aug 4		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2010 Aug 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2011 Feb 24		TOYOTA	Recall	Manufacturer Recall Issued Recall # 90L
2011 Apr 21		TOYOTA	Recall	Manufacturer Recall Issued Recall # B0E
2011 Aug 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2012 Aug 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2012 Oct 10		TOYOTA	Recall	Manufacturer Recall Issued Recall # C0M
2013 Aug 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2014 Aug 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as blue
2014 Sep 4	41,622 KM	Independent Source Winnipeg, Manitoba, Canada	Odometer reading	
2014 Sep 15		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2015 Mar 3		Crown Toyota Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Jul 6	36,429 KM	Crown Toyota Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Aug 14		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2016 Feb 17		TOYOTA	Recall	Manufacturer Recall Issued Recall # G0F
2016 Apr 22	43,322 KM	Crown Toyota Scion Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Aug 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Aug 10		TOYOTA	Recall	Manufacturer Recall Issued Recall # G0V
2016 Nov 4		Crown Toyota Scion Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Jan 13	47,133 KM	Crown Toyota Scion Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Jun 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 May 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2019 Aug 23		Insurance Records British Columbia, Canada	COLLISION	
2019 Aug 23		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2020 May 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Oct 29	112,693 KM	Kal Tire 044 Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2021 Feb 3	114,836 KM	Pennzoil 10 Minute Oil Change Centre Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2021 May 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2021 Sep 17	122,439 KM	Pennzoil 10 Minute Oil Change Centre Kamloops, British Columbia, Canada	Service Record	Vehicle serviced
2022 Jul 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2023 Jul 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2024 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue

ITMBD33V386058442

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2025 Jul 25	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as blue
2026 Jul 5	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as blue



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/veh/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

